

## Monthly Activity Report March 2025

Answered phone calls from residents and dealt with them accordingly.

Made sure park trash was emptied, and parks are in working order.

Monthly playground and storm water inspections.

Cleaned shop area along with offices and break area.

Cold patch any necessary holes within the township.

Clean and make repairs to restrooms within the township parks.

Clean back lot at the Exeter property.

Mulch the flower bed within the parks and administration building.

Install new edging around the flower beds at administration building.

Make repairs to fence at shop area from the high winds over weekend.

Clean dump trucks free from salt.

Patched several curbs with the concrete cold patch.

Started to condition base ball fields.

Catch basin repair 3479, 3439 Lakewood Ct.

Catch basin repair two at 6466, 6469 Windlake Ct.

Catch basin repair 6984, 6214 Creekside Way.

Open rest rooms in the parks for the season.

Add mulch to various areas around the police department.

Inspect a concern with the sump line at 1831 King Ave.

Add new storage shelves to the mezzanine and inspect items already stored.

Repair catch basin at 3410 Lakewood Ct.

Assist BCEO in removal of tree resting on pole on Tuley Rd.

Assist BCEO in jetting storm sewer pipe on Morris Rd.

Start mowing the township parks and buildings.

Make preparations for pending storms.

Clean up several downed trees in various areas.